

OFFICE OF THE SUB DIVISIONAL OFFICER, P.W.D
SUB DIVISION, DEOSAR, SINGRAULI (DT.) M.P
BUILDING FITNESS CERTIFICATE
(To be filled by the Inspecting Officer)

Name of the Officer : S.D.O, P.W.D, Sub Div. Deosar
Name of the School : ST.MARY'S SCHOOL
Location with name of Education district/sub dis : Tahasil-Deosar, Dt.Singrauli , M.P486881
Classification of building : 7626.28 Sq.ft(Ground Floor)
: 7149.28 sq.ft(First Floor)
: 2736.52 sq.ft (Second floor)
Total Area : 17512.08sq.ft
Period for which the certificate is issued : 2022-23
Nature of defects, if any :-
(a)Foundation and basement : Not applicable
(b)Superstructure : Not applicable
(c)Doors and windows : Not applicable
(d)Wood works wrought and put up : Not applicable
(e)Roof : Not applicable
(f)Flooring : Not applicable
(g) Miscellaneous (cracks etc.) : Not applicable

Any major defects noticed which will render the building unsafe in any manner: No

Whether maintenance works have been done properly : Yes

Whether the structure is sound or not for condition classes : Building is sound and safe

Note 1. The stability of the structure should be examined also with reference to location, altitude, intensity of wind, exposure of flood etc.

2. Any additional observations if deemed necessary for the certificate may be furnished separately with this certificate.

CERTIFICATE

Certified that the school building of St.Mary's, Bahera, was inspected by me on 29/12/2021 and found to be fit to conduct classes for the period of 2022-23 for the reasons stated above.

Place: Deosar
Date: 29/12/2021
NO :


084
Sub Engineer
P.W.D. Section Jhurahi
District Singrauli (M.P.)


29/12/2021
Sub Divisional Officer
P.W.D Sub Division Deosar.



316 Englewood
P.M.D. Section Jurchi
High Street (M.P.)


NAME OF :— ST.MARY'S SCHOOL BUILDING, VILL.—BAHERA, P.O.—JYAWAN, TEH.—DEOSAR, DISTT.—SINGRAULI, M.P.



GROUND FLOOR PLAN FOR SCHOOL BUILDING

THE ENGINEER
S.S.D. Section Journals
P.W.D. Section Journals
S.R.C. Section Journals


NAME OF :- ST.MARY'S SCHOOL BUILDING, VILL.-BAHERA.P.O.-JLYAWAN, TEH.-DEOSAR, DISTT.-SINGRAUH M.P.



FIRST FLOOR PLAN FOR SCHOOL BUILDING

Der Standpunkt

NAME OF :— ST.MARY'S SCHOOL BUILDING, VILL.—BAHERA, P.O.—JIYAWAN, TEH.—DEOSAR, DISTT.—SINGRAULI, M.P.



SECOND FLOOR PLAN FOR SCHOOL BUILDING

1284
M.Engg.
A.M.D. Section Jajpur
Rajiv Singhrauli (M.P.)